



GARY R. HERBERT
Governor
GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

May 24, 2013

Reviewed: PRJ

Mine Name: Crescent Creek/May Day Mill	Permit Number: S/017/0043
Operator Name: Martinique Mining	Inspection Date: 05/21/2013
Inspector(s): Wayne Western	Time:
Other Participants: John Reay (BLM)	Mine Status: ACT
Weather Condition: 70's clear skies	Last Inspection: June 21, 2011
Bond Renewal Date: 06/01/2014	Bond Amount: \$12,000
Surface Ownership: BLM	Mineral Ownership: BLM
Last Year of Production: 2008	Acreage: 2 acre

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer,	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Bond/Bond Release	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Annual Fees	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
4. Annual Report	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
6. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This was a routine inspection.

Inspection Summary:

The bond is current.

The annual permit fees have not been paid for 2013.

The annual report has not been filed for 2013


During the inspection the Division found oil spill that contaminated the soil. See pictures. The Permittee needs to remove the contaminated soils. The Permittee also needs to store fluids in a secondary containment facility to that in the event of a spill the soils will not be contaminated.

Conclusions and Recommendations:

The Division should take action about the oil spills, unpaid annual fees and failure to submit an annual report.

Directions to Site:

Inspector's Signature

A handwritten signature in blue ink, appearing to read "Wayne Weir", is written over a horizontal line.

WHW:

cc: (OPERATOR)

John Reay, Hanksville BLM

Sue Fivecoat Hanksville BLM

O:\M017-Garfield\S0170043-CrescentCreek\inspections\Insp05212013.doc



Oil spill strong petroleum smell



Another oil spill



Ponds with liners



Another oil spill